


LCP#	NORTHING	EASTING
900	2078167.4275	6216177.3196
901	2078057.5358	6216146.5719
1300	2071210.7086	6218031.5307
1301	2070657.4551	6218064.2835



LEGEND

- CORNER FOUND PER MAP CASE 2, DRAWER 40, PAGE 66
- ▲ CORNER SET AS NOTED
- 3/4" IRON PIPE PLUGGED RCE 21908
- SET MONUMENTS AS NOTED
- ⊙ FOUND CORNER AS DESCRIBED
- () RECORD BEARINGS AND DISTANCES AGREE WITH THIS SURVEY UNLESS SHOWN OTHERWISE. RECORD DATA FROM:

1. GLO
2. MAP CASE 2, DRAWER 11, PAGE 73, M.C.R.
3. MAP CASE 2, DRAWER 28, PAGE 60, M.C.R.
4. MAP CASE 2, DRAWER 40, PAGE 66, M.C.R.
5. MAP CASE 2, DRAWER 45, PAGE 83, M.C.R.
6. RECORD DATA PER BOOK 1590 O.R. PAGE 338, M.C.R.
7. RECORD DATA PER BOOK 1590 O.R. PAGE 339, M.C.R.
8. RECORD DATA PER INSTRUMENT NO. 2011-01768

AMENDED PARCEL MAP
 OF A PARCEL SUBDIVISION NUMBER P1-2007
 BEING A PORTION OF SECTIONS
 20, 21, 28, 29, 30, 32 AND 33.
 T.12N., R.12W., M.D.M.
 MENDOCINO COUNTY, CALIFORNIA, SEPTEMBER, 2011

AMENDED MAP

TO CORRECT INSUFFICIENT LINE WEIGHT OF
 SECTIONAL BREAKDOWN LINES AS SHOWN
 IN MAPS, DRAWER 82, PAGES 4 THROUGH
 19, M.C.R.

SHEET 5 OF 16

MAPS
 DRAWER 82
 PAGE 34